

SECRET

OUT52416

SECRET 061807Z

25X1

1963 DEC 6 18 25Z

6 DEC 1963

1. SUBJECT. EVALUATION OF CAMERA B 13.

2. A CAMERA MALFUNCTION WAS NOTED AT LEAST ONCE ON FOUR OF THE LAST FIVE GOLDEN TREE MISSIONS FLOWN WITH CAMERA 13. IN THIS MALFUNCTION THE NORMAL POSITION SEQUENCE IS INTERRUPTED BY TWO CONSECUTIVE VERTICALS, ONE OF WHICH IS BLURRED. RECOMMEND THAT THE CAMERA FIELD REPRESENTATIVE INVESTIGATE THIS PROBLEM.

SECRET

END OF MESSAGE

HFS

CJS

CPC

PMS

ACL

Grace (File)

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification